

The firmware update will add the rear camera instant on feature your Axxera stereo .

Introduction

Please download and print this **Firmware Update** procedure prior to downloading and installing this firmware update. **It is important that this procedure is done in the order described in this document as failure to do so may result in your Axxera stereo becoming inoperable.**

Please confirm your Axxera stereo model number installed in your RV and confirm you download the correct model firmware update. Installing the incorrect firmware for your stereo will result in your Axxera stereo becoming inoperable.

Warning: Do not perform this firmware update while operating the vehicle. Do not interrupt the power of the Axxera stereo while the update is in progress. Do Not remove the USB drive until the entire procedure is completed. Remember to record all the “User Settings” prior to performing the update process, as the unit will return to factory default settings after the update.

Requirements

- A **Windows** PC with an internet connection and a Zip/Unzip program installed into it. (<http://winzip.com/downwz.htm>).
- A **blank** USB flash drive with 10KB or greater of memory.

1. Preparation

- 1) Download the matching firmware file for your stereo model and save it to your computers desktop. The files are zip-compressed and you will need to unzip it onto your PC.
- 2) Copy the dvdrom.bin file to a blank USB flash drive.

2. Update

- 1) Power stereo on.
- 2) Insert USB flash drive into USB port of Axxera stereo.
- 3) Touch the Green checkmark icon to begin update.

**Warning: Do not disrupt power during update process.
The stereo will automatically turn off when update is complete.**

- 4) When stereo turns off the update is complete. Remove USB flash drive.

3. Confirm Result

- 1) Remove USB flash drive.
- 2) Power stereo on.
- 3) Enter Setting Menu of stereo.



- 4) On **General Tab**, touch down arrow to find **Version**. Touch on **Version**.
- 5) Confirm Software Version matches your model:

AVM101	90830A
AVN6558BT	190830AA