

APP software update:

1: Format the USB.

2: Copy the two files "ISPBOOOT.BIN" and "ISPBOOOT_UPDATE.BIN" into USB device

3: Power off the headunit, then insert the USB device to USB slot (Please use rear USB for software update).

4: Power on the headunit, you will see the below pic on the LCD.



5: APP software update will take about 90 second, then you will see the below pic on the screen.



6: Remove the USB , Power off -->Power on. APP software update is completed successfully.


MCU software update

1: Format the USB.


2: Copy the two files "Download.bin" and "sppf_mcu32.img" into USB device

3: Power off the headunit, then insert the USB device to USB slot (Please use rear USB for software update).

4: Power on the headunit, you will see the below pic on the LCD.



5: MCU software update will take about 30 seconds. Then you will see the below pic on the screen.



6: Remove the USB and press "ok", MUC software update finished.